

Nomad SERVICE LETTER

99-3

WIPER BLADE ASSEMBLIES

INSTRUCTIONS

1. Insert Service Letter 99-3 into the Service Letter binder and annotate the index accordingly.

CONTENT

2. Service Letter 93-1 was issued to alert Operators to the provisions of Rosemount Inc. Service Bulletin 2315-30-04 (July 10, 1992) which defined a service life for the entire wiper blade assembly.
3. In the accomplishment instructions of Para 2.B. of the Service Bulletin, the part numbers are incorrectly stated for the left and right installations.
4. The correct part numbers for fitment to Nomad aircraft are as follows:

Left or Pilots side - 2315M-4 and

Right or Co-pilots side - 2315M-2

VIC BIBBY
TECHNICAL SERVICES MANAGER
NOMAD TECHNICAL SUPPORT

SL 99-3

Page 1/2
1 October 1999