



A Mahindra Aerospace Company

PO Box 881, Morwell, Victoria 3840, Australia

Ph + 61 (0) 3 5172 1200

Fax + 61 (0) 3 5172 1201

www.gippsaero.com

**SB-GA8-2012-91**

**Issue 1**

**OPTIONAL**

# Service Bulletin

---

## **Subject:**

Installation of headset jacks and associated wiring

## **Applicability:**

All GA8 Serial numbers.

## **Amendments:**

1: Initial Issue.

## **Background:**

This Service Bulletin covers the installation of headset jacks and associated wiring for each passenger in the GA8.

## **Compliance:**

For applicable aircraft this optional Service Bulletin may be incorporated at the owner's discretion.

## **Labour:**

6 hours should be allocated to the incorporation of this Service Bulletin.

## **Warranty:**

Aircraft within the warranty period may claim from GA-warranty@gippsaero.com

## **Approval:**

This modification has been approved pursuant to Regulation 21.095 of CASR (1998).

## **Weight and Balance:**

Installation of the headset jacks with associated looms represents a weight increase of 0.42 kg (0.93 lbs) at a fuselage station of 1,660 mm (65.5 in) aft of datum.

## **Parts:**

Refer to the Bill of Materials (BOM) specified on the drawings. See Installation section for drawing locations.

## Parts Availability:

New parts can be purchased directly from GippsAero.

Tel: +61 (0)3 5172 1200

Fax: +61 (0)3 5172 1201

Email: [spares@gippsaero.com](mailto:spares@gippsaero.com)

## Installation:

The headphone jacks and wiring installation (P/N GA8-233004-1) is to be installed in accordance with the following GippsAero drawings:

Drawing	Sheet	Issue
GA8-233004	1	2
GA8-231011	1	5
GA8-231011	2	3

## Documentation:

Update the aircraft log book to reflect incorporation of this Service Bulletin.

## Continuing Airworthiness:

Maintenance of the installed alternator shall be carried out in accordance with the GippsAero GA8 Service Manual.

## Compliance Notice:

Complete the Document Compliance Notice and return to GippsAero by mail, fax or email.

## DOCUMENT COMPLIANCE NOTICE



A Mahindra Aerospace Company

Document:

**SB-GA8-2012-91**

**Issue 1**

Aircraft Serial Number: GA8-\_\_\_\_\_

Service Bulletin SB-GA8-2012-91 Issue 1 has been incorporated in the above aircraft.

Date: \_\_\_\_\_

\_\_\_\_\_

Signed

Print Name: \_\_\_\_\_

Please post or fax this compliance notice to:

GippsAero  
Attn: Technical Services  
P.O. Box 881  
Morwell Victoria 3840  
Australia  
Fax.: +61 03 5172 1201